

Carry cases and adapters

Carry cases for magnetic core drilling machines and EKF edge processing machines. Adapters for drill chuck and gear rim drill chuck.

Carry cases for magnetic core drilling machines

The new carry cases developed by BDS for magnetic core drilling machines have many benefits.

- ▶ Portable – low weight with high level of stability at the same time.
- ▶ Closed firmly – secure and large mechanical locks.
- ▶ Sealed – the contents are protected completely against dust and spray water.
- ▶ Roll along instead of carry – ABS wheels and telescopic grip.

BDS Maschinen develops products from the ergonomic points of view.

The new carry case provided with wheels for magnetic core drilling machines of the MAB 1300 series has large, robust ABS wheels and a telescopic grip, which facilitate transporting the heavy machine to a large extent and make it safe.

The MAB 1300 is fitted safely and securely in robust plastic bowls that absorb the heavy weight of the machine ideally.



HARD PROTECTIVE CASE

ORD. NO. SUITABLE FOR

ZHK 100 MAB 100, MAB 150

ZHK 400 MAB 455, MAB 485, MAB 525

Application: Carry case for BDS magnetic core drilling machines. **Design:** Robust hard cover case with handle and stable clasps. With foam padding, no contents.

CARRY CASE

ORD. NO. SUITABLE FOR

ZPK 001 EKF 300, EKF 450, EKF 452

Application: Carry case for EKF 300, EKF 450 and EKF 452.

Design: Plastic case with handle and foam padding, no contents.



CARRY CASE ON WHEELS

ORD. NO. SUITABLE FOR

ZHK 1300 MAB 1300

Application: Carry case on wheels for BDS magnetic core drilling machines. **Design:** Robust carry case on wheels with handle and stable clasps. No contents.



CARRY CASE ON WHEELS

ORD. NO. SUITABLE FOR

ZHK 825 MAB 825, MAB 845

Application: Carry case on wheels for BDS magnetic core drilling machines. **Design:** Robust carry case on wheels with handle and stable clasps. No contents.



The robust carry case on wheels.

BDS hard cover cases and carry cases on wheels are robust, watertight and shockproof.



1. Connect adapter to drill chuck.



2. Place drill chuck in direct arbor.



3. Ready for use with twist drill.

For magnetic core drilling machines with direct arbor
19 mm Weldon ($\frac{3}{4}$ ")

- ProfiSTART** MAB 100
- ProfiBASIC** MABasic 200
MABasic 400
- ProfiSPEZIAL** AutoMAB 1500
AkkuMAB 3000



ADAPTER FOR DRILL CHUCKS

ORDER NO.

ZAP 100
Weldon shank 19 mm ($\frac{3}{4}$ ") to $\frac{1}{2}$ " x 20 NF



GEAR RIM DRILL CHUCK

ORD. NO. INTERNAL THREAD CLAMP SIZE

ZBI 113	$\frac{1}{2}$ " x 20 NF	1 - 13 mm
ZBI 116	$\frac{1}{2}$ " x 20 NF	2.5 - 16 mm



QUICK-ACTION DRILL CHUCK

ORD. NO. INTERNAL THREAD CLAMP SIZE

ZSI 113	$\frac{1}{2}$ " x 20 NF	1 - 13 mm
ZSI 116	$\frac{1}{2}$ " x 20 NF	3 - 16 mm



1. Connect taper drift to drill chuck.



2. Place drill chuck in MT arbor.



3. Ready for use with twist drill.

For magnetic core drilling machines with Morse taper MK 2 or MK 3.

- ProfiPLUS** MAB 485 / 485 SB
MAB 485
MAB 525 / 525 SB
MAB 825 / 845 SB
MAB 1300
- ProfiSTART** MAB 455 / 455 SB
MAB 855
- ProfiBASIC** MABasic 450
- ProfiSPEZIAL** AirMAB 5000



TAPER DRIFT FOR DRILL CHUCK

ORDER NO.

ZKD 216	DIN 238 - MK 2/B16
ZKD 316	DIN 238 - MK 3/B16



GEAR RIM DRILL CHUCK

ORD. NO. INTERNAL THREAD CLAMP SIZE

ZBK 113	DIN 238-B16	1 - 13 mm
ZBK 116	DIN 238-B16	2.5 - 16 mm



QUICK-ACTION DRILL CHUCK

ORD. NO. INTERNAL THREAD CLAMP SIZE

ZSB 113	DIN 238-B16	1 - 13 mm
ZSB 116	DIN 238-B16	3 - 16 mm



KEY FOR GEAR RIM DRILL CHUCK

ORDER NO.

ZEZ 113
ZEZ 116



CHIP PROTECTION

ORD. NO. MACHINE

ZSS 050	MAB 100 – MAB 525
ZSS 500	MAB 825 – MAB 855



DRILL DRIFT DIN 228

ORD. NO. SIZE DIN STANDARD

ZAS 002	MK 2	DIN 228
ZAS 003	MK 3	DIN 228

SAFETY CHAIN

ORDER NO.

ZSK 001

PUMP BOTTLE

ORDER NO.

ZKP 100

